## **SAUNA CRAFT HI-LIMIT RESET**

Capillary Type (green stem/button).

Typically, when heater hi-limit trips, the control will still work. controls with pilot light or digital display should still be "on", but there will be no heat.

Using a pencil or similar, press the green button slight. The heater should re-set and begin working immediately.

If hi-limit trips repeatedly, call a service technician or call for trouble-shooting assistance.



